Date:

Friday, 21/09/2007 9:20:26 AM

User:

Linda Lacelle

Process Sheet

Customer Job Number : CC-DAR01 Dart Aerospace Ltd.

: 34757

Estimate Number P.O. Number

: 10804

This Issue Prsht Rev.

First Issue

Written By

Previous Run

: NIA : 21/09/2007

S.O. No. : NLA

: 00015

: LANDING GEAR

Type

Part Number

Drawing Name

: D3289041

: D3289-041

Drawing Number

: SCRAP-ECN 1028

Project Number Drawing Revision

NA:

Material **Due Date**

Qty:

1 Um:

Each

Comment **Additional Product**

Checked & Approved By

Job Number:



Seq. #:

Description:

1.0 LANDING GEAR 1

LANDING GEAR RESOURCE 1



Comment: LANDING GEAR RESOURCE 1

REMOVE FROM STK:

Scrap on original W/O

3 X D3289-041 B24864

SCRAP PARTS PER ECN 1028 / EMAIL BILL/LINDA SEPT. 14TH

2.0

3.0

D3289041

Float Web (206A/B)



Comment: Qty.:

1.0000 Each(s)/Unit Total:

1.0000 Each(s)



QC21

Float Web (206A/B)

FINAL INSPECTION/W/O RELEASE



Comment: FINAL INSPECTION/W/O RELEASE

Job Completion







Under Review Notification

Raised By: MARC BELLAVANCE

Date: 07.09.04

Product #: D206-642-641

Product Name: HIGH GEAR FLOAT SKIDTUBE

Drawing/Kit Number	Drawing/Kit Description	Quantity on Hand (Stock)	Quantity on Order (Production)	Quantity Allocated (Customer Order)	HOLD SHIPMENT	Red Tag/Quarantine Stock	Advise customers	Stop Production	Re-Work Stock	IPP Under Review	Blue File Under Review	ECN#	Instructions
D3288	SKIDTUBE ASSEMBLY	N	N	N	N	N	N	N	N	·Υ	Υ	1028	N/A
D3289	FLOAT WEB, 206A/B	Y	Υ	Y	Υ	Υ	Υ	Ν	N	Υ	Υ	1028	QUARANTINE STOCK, GET ENG. APPROVAL
													PRIOR TO SCRAPPING ITEMS
	4- B32782												
3	8- SHK B24864						,						
, , ,													

Description of issue:

THE NEW REVISION WILL ADDRESS A COMPATIBILITY ISSUE WITH SOME GROUND HANDLING WHEEL UNITS. THE MID-FLOAT WILL BE MOVED 2" FWD, AND ROTATED 16 DEGREES INBOARD TO PROVIDE ADEQUATE CLEARANCE. NOTE: D3288 AND D3289 AFFECT D206-642-641 WHICH IN TURN AFFECTS D206-642-611/-612/-613/-614.

Distribution:

General Manager

Production Manager

Director Quality Assurance

Design Manager

Chief Engineer

Production Engineering Coordinators

Quality Assurance Coordinator

Quality Control Coordinator

Order Processing

Customer Technical Support

Engineering Project Managers

Engineering Clerk

Marketing

Jason Murdoch

From:

Marc Bellavance [mbellavance@dartaero.com]

Sent:

Monday, September 17, 2007 7:46 AM

To:

'Jason Murdoch'

Subject:

RE: -- UNDER REVIEW - D3288 REV. D & D3289 REV. C --

Follow Up Flag: Follow up

Flag Status:

Red

Attachments:

URF D3288-D3289.pdf

Jason,

As per Under Review Form sent on 07.09.06 (attached), you can assign ECN#1028 as a reference to scrap the parts.

Marc Bellavance Internal Support/Product Improvement

DART aerospace Ltd.

Tel: 613-632-5200 Ext. 240

Fax:

613-632-9311

E-mail: mbellavance@dartaero.com

Web: www.dartaero.com

From: Jason Murdoch [mailto:jmurdoch@dartaero.com]

Sent: September 17, 2007 7:22 AM

To: 'Marc Bellavance'

Subject: FW: -- UNDER REVIEW - D3288 REV. D & D3289 REV. C --

Can I get an ECN # for this? And I'll sign the ECN if it is ready.

jmurdoch@dartaero.com Q.C. COORDINATOR

From: Bill Beckett [mailto:bbeckett@dartaero.com]

Sent: Friday, September 14, 2007 3:00 PM

To: 'L Lacelle'; 'Jason Murdoch'

Subject: RE: -- UNDER REVIEW - D3288 REV. D & D3289 REV. C --

Agreed.

Bill

From: L Lacelle [mailto:llacelle@dartaero.com]

Sent: September 14, 2007 8:30 AM

To: 'Jason Murdoch'; bbeckett@dartaero.com

Subject: RE: -- UNDER REVIEW - D3288 REV. D & D3289 REV. C --

I say scrap

From: Jason Murdoch [mailto:jmurdoch@dartaero.com]

Sent: September 14, 2007 8:23 AM **To:** bbeckett@dartaero.com; 'L Lacelle'

Subject: FW: -- UNDER REVIEW - D3288 REV. D & D3289 REV. C --

New hand. So what's the deal??

jmurdoch@dartaero.com O.C. COORDINATOR

From: Marc Bellavance [mailto:mbellavance@dartaero.com]

Sent: Friday, September 14, 2007 8:01 AM

To: 'Jason Murdoch'
Cc: 'Mike Petsche'

Subject: RE: -- UNDER REVIEW - D3288 REV. D & D3289 REV. C --

Here is the deal:

In short, this is to address a compatibility issue.

In length, as per Under Review Form, the mid float bag requires to be re-positioned 2" fwd and rotated 16.5 degrees inboard to ensure proper clearance when using some ground handling wheels units.

If we send those tubes to customers, chances are they will return them due to incompatibility. As for scrapping the parts, I would scrap them but I am not authorized to make that call. Please see Bill and/or Linda.

Marc Bellavance Internal Support/Product Improvement

DART aerospace Ltd.

Tel: 613-632-5200 Ext. 240

Fax: 613-632-9311

E-mail: mbellavance@dartaero.com

Web: www.dartaero.com

From: Jason Murdoch [mailto:jmurdoch@dartaero.com]

Sent: September 13, 2007 6:04 AM

To: 'Marc Bellavance'

Subject: RE: -- UNDER REVIEW - D3288 REV. D & D3289 REV. C --

Good day. What is going on with these, parts? Are they going to be scrapped?

jmurdoch@dartaero.com Q.C. COORDINATOR

From: Marc Bellavance [mailto:mbellavance@dartaero.com]

Sent: Thursday, September 06, 2007 3:07 PM

To: 'Beckett, Bill'; 'Campbell, Daniel'; 'Charbonneau, Eric'; 'Elsliger, Leanne'; 'Fuentes, Roberto'; 'Hum, Petter'; 'Johnston, Kim'; 'Lacelle, Linda'; 'Menard, Jean-Luc'; 'Murdoch, Jason'; 'Petsche, Mike'; 'Provencal, Chris';

'Sheldon, Susanne'; 'Shepherd, David'; 'Stow, Dan'; 'Trepanier, Dale'; 'Willems, Sian'

Subject: -- UNDER REVIEW - D3288 REV. D & D3289 REV. C --

Drawings D3288 Rev. D and D3289 Rev. C are now under review per attached form.

Marc Bellavance Internal Support/Product Improvement

DART aerospace Ltd.

613-632-5200 Ext. 240 Tel:

613-632-9311 Fax:

E-mail: mbellavance@dartaero.com
Web: www.dartaero.com